

Report No: 32 (04/09/18 - 04/13/18)
Prepared by: Kalee Erickson
Average Temperature: 55°F
Week's Precipitation: 0.55"
Weekly Craftperson Count: 25

OWNER

Riverview Retirement Community
1801 East Upriver Drive
Spokane, WA 99207
509.482.8100
www.riverviewretirement.org

**GENERAL
CONTRACTOR/
CONSTRUCTION
MANAGER**

Bouten Construction Company
627 North Napa Street
Spokane, WA 99220
509.535.3531
www.boutenconstruction.com

ARCHITECT

NAC Architecture
1203 West Riverside Avenue
Spokane, WA 99201
509.838.8240
www.nacarchitecture.com



Lance Pounder Excavating paved where the sewer main tap occurred



Riverside Exteriors installed lap side on the North elevation



LAC Drywall applying fluid weather barrier to soffit



LAC Drywall fire taping above-ceiling

Upcoming Construction Activity

- Interior rough-in is ongoing.
- Exterior siding is ongoing.
- Framing and plumbing wall inspection will occur next week in Zone 2.